OSI

Technical Service Department *30031 Ahern Ave. Union City, CA 94587-1234*
Phone: 800-777-4674 *Fax: 510-429-8324* *Email:Technicalservices@osiosi.com*

5838 Andrews Table Replacement Parts

Description	Part Number
Caster, Foot-end (Individual brake, **item 11** below)	5820-496
Caster, Head-end (Dual braking, **item 10** below)	5820-495
Heel Clamp Release Button (2 required)	5820-799
Heel Cup (2 required, **item 8** below)	5820-371
Hydraulic Cylinder, Trendelenburg (**item 13** below)	5820-478
Hydraulic Cylinder, Column (Table Height, **item 14** below)	5820-482
Hydraulic Cylinder, Torso Lift (**item 15** below, not mounted)	5837-51
Hydraulic Cylinder, Foot End (**item 16** below)	5820-479
Hydraulic Cylinder, Slider (Tibial Support, **item 18** below)	5820-481
Hydraulic Cylinder, Lateral Tilt (below Motor/Pump)	5837-50
Hydraulic Filter Assembly	5820-499
Hydraulic Manifold Assembly (**item 12** below)	5820-485
Hydraulic Motor/Pump (**item 17** below)	NL1244
Hydraulic Selector Valve Knob (6 required)	5820-356
Hydraulic Selector Valve Assembly (6 required)	5820-486
Lock Handle, Autoglide Torso Lift	5820-357
Lock Handle, Hip Support (2 required)	914-424
Lock Handle, Seat Adjustment (2 required)	5820-342
Lock Handle, Seat Pivot	914-413
Pad, Arm Board (Shearguard Gel, 2 required, **item 1** below)	5830-19
Pad, Autoglide Torso Lift (Shearguard Gel, **item 3** below)	5830-30
Pad, Head	HB5820-630
Pad, Lateral Hip Support (2 required, **item 4** below)	5820-607
Pad, Iliac Bolster (2 required)	5820-620
Pad, Seat (**item 5** below)	5820-600
Pad, Tibial (Shearguard Gel, **item 7** below)	5830-20
Pad, Thigh (Femoral, **item 6** below)	5820-660
Pad, Torso Right	5820-685
Pad, Torso Left (**item 2** below)	5820-686
Patient Hip Sling	5820-610
Patient Iliac Crest Sling (2 required)	5820-620
Power Cord Assembly	5837-22
Power Cord strain Relief	5892-132
Switch, Foot (**item 9** below)	NV0440
Switch, ON/OFF Power (Circuit Breaker)	NV0311
Table Storage Cover	5820-655

OSI

Technical Service Department *30031 Ahern Ave. Union City, CA 94587-1234*

Phone: 800-777-4674 *Fax: 510-429-8324* *Email:Technicalservices@osiosi.com*



Andrews Table – Left-side View



Andrews Table – shown without sheet-metal covers, pads, or final assembly parts.